

Date: 30/09/2021

Ref: 2021MTM430/G007/2021

## إنذار ملاحى

### NAVIGATION WARNING # G007/2021

#### The Drifted Buoy has been Removed

Further to Navigational Warning #G006/2021, this is to inform all the stations that the drifted buoy has been removed.

Navigational Warning # 2021MTM430/G006/2021 issued on 29<sup>th</sup> Sep. 2021 have been cancelled.

All VTS (Hamriyah port, Khor Dubai, Port Rashid, Fishing Harbours and Jabal Ali Port) are requested to advise vessels accordingly.

Owners, Agent, Charters, Marinas, Yacht club and Recreational Sailing Organizations shall ensure that the contents of this notice are made known to the masters or persons in charge of their vessels.


#### تم إزالة العوامة الملاحية الجانحة

بالإشارة للإنذار الملاحى رقم (G006/2021)، هذا لإعلام كافة المحطات بأنه قد تم إزالة العوامة الملاحية الجانحة.

إعتبار الإنذار الملاحى بمرجع رقم (2021MTM430/G006/2021) الصادر بتاريخ 2021/09/29 لاغياً.

على جميع العاملين على نظام متابعة الوسائل البحرية في (ميناء الحميرية، وخور دبي وميناء راشد، ومرافق الصيد وميناء جبل علي) إبلاغ الوسائل البحرية بهذا الخصوص.

على مالكي السفن، والوكلاء، والمستأجرين، والمراسي، ونوادي اليخوت والقوارب الترفيهية والشراعية الإلتزام بإبلاغ قباطنة الوسائل البحرية أو الأشخاص المسؤولين على متنها بتطبيق محتويات هذا الإنذار .

  
محمد آل حريز  
مدير الممرات المائية  
سلطة مدينة دبي الملاحية

