

Date: 18/11/2019

Ref: MO/MTM/NW/G013/2019

## إنذار ملاحية

### NAVIGATION WARNING # G013/2019

Crescent Island Area in the vicinity of Position 25° 18.00' N, 054 41.20 ' E are strictly Prohibited

منطقة محظورة بالقرب من جزيرة الهلال في الموقع  
25° 18.00'N, 054 41.20 'E

This is to inform all the stations Crescent Island Area in the vicinity of Position 25° 18.00'N, 054 41.20 'E are strictly Prohibited map as attached. The Restricted Area are Marked by buoys as below:

هذا لإعلام كافة المحطات بالمنطقة المحظورة بالقرب من جزيرة الهلال في الموقع 25° 18.00'N, 054 41.20 'E والتي ستكون حسب الخرائط المرفقة منطقة محظورة و ستكون محددة بالعوامات الملاحية التالية:

S	AtoN'sName	Coordinates	
1	MIS (Special Mark)	25° 17.860'N	054° 41.250' E
2	MINC (North Cardinal)	25° 18.360'N	054° 41.250' E
3	MIEC (East Cardinal)	25° 17.860'N	054° 41.750' E
4	MISC (South Cardinal)	25° 17.360'N	054° 41.250' E
5	MIWC (West Cardinal)	25° 17.860'N	054° 40.750' E

م	اسم العوامة	الإحداثيات	
1	MIS (Special Mark)	054° 41.250' E	25° 17.860'N
2	MINC (North Cardinal)	054° 41.250' E	25° 18.360'N
3	MIEC (East Cardinal)	054° 41.750' E	25° 17.860'N
4	MISC (South Cardinal)	054° 41.250' E	25° 17.360'N
5	MIWC (West Cardinal)	054° 40.750' E	25° 17.860'N

The two old Isolated Danger Marks have been removed.

تمت إزالة العوامتين الملاحيتين القديمتين.

All vessels in the area are advised to give wide berth and shall navigate with extreme cautions.

كافة الوسائل البحرية العاملة في المنطقة إعطاء مسافة كافية والإبحار بحيطه وحذر شديدين.

All VTS (Hamriyah port, Khor Dubai, Port Rashid, Fishing Harbours and Jabal Ali Port) are requested to advise vessels accordingly.

على جميع العاملين في (ميناء الحميرية، وخور دبي وميناء راشد، ومرافق الصيد وميناء جبل علي) تقديم المشورة للسفن للحفاظ على هذه المنطقة خالية.

Owners, Agent, Charters, Marinas, Yacht club and Recreational Sailing Organisations shall ensure that the contents of this notice are made known to the masters or persons in charge of their vessels.

على مالكي السفن، والوكلاء، والمستأجرين، والمراسي، ونوادي اليخوت والقوارب الترفيهية والشراعية الإلتزام بإبلاغ قباطنة الوسائل البحرية أو الأشخاص المسؤولين على متنها بتطبيق محتويات هذا الإنذار.

خميس ولد عميل  
مدير إدارة حركة المرور البحرية  
سلطة مدينة دبي الملاحية




Page 1 of 2



# Crescent Island

Aid to Navigation

## Legend



AtoN Name	Buoy Description	Co-ordinates		Flash Codes	Visibility
		Northing	Easting		
MIS	Special Marker	25°17'.860"	54°41'.250"	FL 5S; Yellow	2-3nm
MINC	North Cardinal	25°17'.360"	54°41'.250"	Q 1.2S; White	3-5nm
MIEC	East Cardinal	25°17'.860"	54°41'.750"	Q (3)10S; White	3-5nm
MISC	South Cardinal	25°17'.360"	54°41'.250"	Q (6) +LFL 15S; White	3-5nm
MIWC	West Cardinal	25°17'.860"	54°41'.750"	Q (9)15S White	3-5nm

Activate Windows  
Go to Settings to activate Windows

4000 ft